


Building Safety Certificate

The School Building of Maharishi Vidya Mandir School Dangoh Khas (Daulatpur Chowk) Tehsil Ghanari Distt. Una (HP) inspected by the Junior Engineer (Section Daulatpur-II) It has been observed that no earth quake resistant provisions has been adopted for this building and no structural drawing is approved by the competent Govt. certified Engineer has been produced at the time of inspection and moreover no assistance was taken from Public Works Department for construction of the building. Hence the structural safety of this building cannot be assured specially from earthquake resistance point of view. This department will not be held responsible for any type of loss of life and property etc. if this structure fails under any circumstances However as per visual inspection of the building, it has been found safe at present stage only for the year 2021-22.


Assistant Engineer,
Gagret Sub Division,
HPPWD, Gagret.


Executive Engineer
Bharwain Division
HPPWD, Bharwain